


SEASTAR/BAYSTAR NYLON TUBING LOT# 71335 AND 71336

Through in-house testing Teleflex Canada has found an isolated failure with our SeaStar/Baystar Nylon Tubing, Lot# **71335/71336**. This may result in loss of steering causing property damage and/or personal injury. Please read the following inspection procedure and ensure you follow **ALL** instructions prior to your boats next use.

Step 1

Locate the 'lot number' on the SeaStar/Baystar Nylon Tubing. (Refer to figure A.) Check **ALL** tubing on board your boat for this Lot number. If your tubing is **NOT** marked Lot# '**71335**' or '**71336**', or is marked with a different number, please go to Step 3.



Step 2

If any of your boats tubing is marked with Lot# '**71335**' or '**71336**' (refer to figure A), this tubing must be removed and replaced prior to your boats next use. Please contact our **Warranty Department toll free at 1-866-779-6899** for replacement parts.

Step 3

Periodic maintenance/system check as per your installation manual: Once the new tubing has been installed, or, you have determined that your tubing is **NOT** from Lot# '**71335**' or Lot# '**71336**', please perform the following with a **fully purged system**:

- i) Turn the steering wheel very hard to port and pressurize the system, i.e. turn the wheel past the hard over position by applying sufficient force to exceed the pressure relief (this will not harm the steering system).
- ii) Check ALL the port fittings and the tubing connections for any leaks. If leaks are found, repair as required. If no leaks are found, the port side is ready for use.
- iii) Repeat steps i and ii turning the steering wheel to starboard.
- iv) Your boat is now ready for its next use.