

OPTIMUS HYDRAULIC PUMP BRACKET CHANGE

APRIL, 2020



Mobile living made easy.

 **DOMETIC**

OPTIMUS HYDRAULIC PUMP BRACKET

- Changes
 - EP15XX Optimus steering pump assembly
 - 682154 Mounting Bracket change to 316 stainless steel from painted ASTM-A1008-10CS-TYPE B steel
 - Part number(s) will remain the same
 - Phased in change for the pump bracket
 - Everything else remains the same
- Passed 300 hr salt spray with no corrosion
- Will be implemented as soon as April

WHY THIS CHANGE

Dometic strives to make product improvements and it was part of the continuous improvement program based on customer feedback regarding aesthetics to the bracket after exposure to the environment in a boat.

Stainless steel is more resilient to the environment in a boat and the fact there is no paint, improves the appearance over time.



Summary

- The bracket will be a phased-in change and you will start to see pumps arriving in the April timeframe
- The price will remain the same
- Thank you for your ongoing support for Optimus and the Dometic family of products

A scenic photograph of a couple on a red boat named 'Paradise' docked at a pier. The woman is standing on the boat, and the man is leaning over the side. The background features a calm lake and snow-capped mountains under a clear sky. The text 'DOMETIC MOBILE LIVING MADE EASY.' is overlaid in large white letters.

↗ DOMETIC
MOBILE LIVING
MADE EASY.

Mobile living made easy.

↗ DOMETIC